



PCN # [0470397-00]
Mirco 1000 Firmware Version 2.02.00

Table with 14 sections: 1. Supplier Information, 1.6 Supplier Contact Info, 2. Product Change Notification Number, 3. Issue Date of Change, 4. System Affected, 5. New Product ID, 6. Old Product ID, 7. New CLEI Code, 8. Old CLEI Code, 9. Associated Products or Changes Affected, 10. Drawing Number, 11. Classification of Change, 12. Reason for Classification, 13. Reason for Change, 14.1 Description of Change.



<ul style="list-style-type: none">a. FXM Micro Card Firmware Version 2.02.00<ul style="list-style-type: none">i. Improved thermal management and fan controlii. Fix Automatic Transfer Switch (ATS) dry contact C8 operation on inverterb. SNMP Card Firmware Version 2.01.00<ul style="list-style-type: none">i. Power Outage menu selection fixed in UPS Monitoring and Maintenance section	
14.2 Change Verification Procedures N/A	
15. Safety Notification N/A	
16. Material Affected N/A	
17. Documentation Affected N/A	
18. Supplier Implementation Date Starting in December 2018 units will begin shipping from Alpha factory with updated firmware and software.	19. Modification Completion Date 11/23/2018
20. Modification Location Factory	
21. Modification Cost N/A	
22. Location and Quantity of Equipment N/A	
23. Attachments N/A	
24. Comments Micro 1000 units currently running software lower than V1.08.70R can only be upgraded to V2.02.00 via an RS232 interface using the FXM Programmer application. After upgrading the FXM software, upgrade the Ethernet card. (Future upgrades can be done via the web.) A Micro 1000 currently running software V1.08.00 or later can be upgraded to V2.02.00 via an RS232 interface using FXM Programmer.	