



an EnerSys company

## PCN # [0470448-PCN] Rev. B Ciena Custom PowerWorx Panels Update #1

<b>1. Supplier Information</b> Alpha Technologies, Ltd. 7700 Riverfront Gate, Burnaby, BC V5J 5M4 Canada	<b>1.6 Supplier Contact Info</b> Contact: Gary Thrift Product Manager 604-318-5317 gary.thrift@alpha.ca																		
<b>2. Product Change Notification Number</b> PCN # 0470448-PCN	<b>3. Issue Date of Change</b> 3/10/2020																		
<b>4. System Affected</b> Major System Affected: PWXCNA Subsystem Affected: PowerWorx Ciena Panels Hardware Affected: Y Firmware Affected: N Software Affected: N																			
<b>5. New Product ID</b>  <table border="1" data-bbox="191 1226 769 1339"> <thead> <tr> <th colspan="2">Hardware</th> </tr> <tr> <th>Model</th> <th>Part Number (P/N)</th> </tr> </thead> <tbody> <tr> <td>N/A</td> <td>N/A</td> </tr> </tbody> </table>	Hardware		Model	Part Number (P/N)	N/A	N/A	<b>6. Old Product ID</b>  <table border="1" data-bbox="802 1226 1383 1432"> <thead> <tr> <th colspan="2">Hardware</th> </tr> <tr> <th>Model</th> <th>Part Number (P/N)</th> </tr> </thead> <tbody> <tr> <td>PWX-071FC440YDPWN-C</td> <td>300001734729</td> </tr> <tr> <td>PWX-071FC420YDPWN-C</td> <td>300001734730</td> </tr> <tr> <td>PWX-071FC410YDPWN-C</td> <td>300001736276</td> </tr> <tr> <td>PWX-071FC450YDPWN-C</td> <td>300001736277</td> </tr> </tbody> </table>	Hardware		Model	Part Number (P/N)	PWX-071FC440YDPWN-C	300001734729	PWX-071FC420YDPWN-C	300001734730	PWX-071FC410YDPWN-C	300001736276	PWX-071FC450YDPWN-C	300001736277
Hardware																			
Model	Part Number (P/N)																		
N/A	N/A																		
Hardware																			
Model	Part Number (P/N)																		
PWX-071FC440YDPWN-C	300001734729																		
PWX-071FC420YDPWN-C	300001734730																		
PWX-071FC410YDPWN-C	300001736276																		
PWX-071FC450YDPWN-C	300001736277																		
<b>7. New CLEI Code</b> N/A	<b>8. Old CLEI Code</b> WMPYABDGRB WMPYABUGRA WOMYABPFRA WOMYABRFRA																		
<b>9. Associated Products or Changes Affected</b> N/A																			



an EnerSys company

<b>10. Drawing Number</b> 300001726163	
<b>11. Classification of Change</b> D	<b>12. Reason for Classification</b> This change incorporates minor design improvements
<b>13. Reason for Change</b> Field failures of proper connection from connecting bus bar due to alignment issues	
<b>14.1 Description of Change</b> Modified holes from .201 to .201 x .320 slots	
<b>14.2 Change Verification Procedures</b> Units with a serial number greater than 245017444 have the implemented fix.	
<b>15. Safety Notification</b> N/A	
<b>16. Material Affected</b> 300001726164	
<b>17. Documentation Affected</b> N/A	
<b>18. Supplier Implementation Date</b> N/A	<b>19. Modification Completion Date</b> N/A
<b>20. Modification Location</b> N/A	
<b>21. Modification Cost</b> N/A	
<b>22. Location and Quantity of Equipment</b> N/A	
<b>23. Attachments</b> N/A	



an EnerSys company

**24. Comments**

All units with serial numbers greater than 245017444 will have the implemented fix.