



an EnerSys company

Product Change Notification

PCN # [0470479-PCN]
RBMS Plus Web Version 1.05A

| 1. Supplier Information Alpha Technologies, Ltd. 7700 Riverfront Gate Burnaby, BC V5J 5M4 Canada | 1.6 Supplier Contact Info Contact: Daljit Hothi Product Manager 1.604.422.4490 daljit.hothi@enersys.com | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|--|--|-------|-------------------|-----|-----|--|--|---------------------|--|-------|----------|----------|------|-----------|-------|--|----------|--|-------|-------------------|--------------------|-------------|---------------------|-------------|--|--|---------------------|--|-------|----------|----------|------|-----------|------|
| 2. Product Change Notification Number PCN # 0470479-PCN | 3. Issue Date of Change April 14, 2021 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 4. System Affected Major System Affected: RBMS Plus Subsystem Affected: N/A Hardware Affected: N Firmware Affected: N Software Affected: Y | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 5. New Product ID <table border="1" data-bbox="191 1180 769 1474"> <thead> <tr><th colspan="2">Hardware</th></tr> <tr><th>Model</th><th>Part Number (P/N)</th></tr> </thead> <tbody> <tr><td>N/A</td><td>N/A</td></tr> <tr><td colspan="2"> </td></tr> <tr><th colspan="2">Software / Firmware</th></tr> <tr><th>Model</th><th>Revision</th></tr> <tr><td>Firmware</td><td>1.61</td></tr> <tr><td>Web Files</td><td>1.05A</td></tr> </tbody> </table> | Hardware | | Model | Part Number (P/N) | N/A | N/A | | | Software / Firmware | | Model | Revision | Firmware | 1.61 | Web Files | 1.05A | 6. Old Product ID <table border="1" data-bbox="802 1180 1380 1474"> <thead> <tr><th colspan="2">Hardware</th></tr> <tr><th>Model</th><th>Part Number (P/N)</th></tr> </thead> <tbody> <tr><td>RBMS Plus 1 String</td><td>0370260-002</td></tr> <tr><td>RBMS Plus 2 Strings</td><td>0370260-003</td></tr> <tr><td colspan="2"> </td></tr> <tr><th colspan="2">Software / Firmware</th></tr> <tr><th>Model</th><th>Revision</th></tr> <tr><td>Firmware</td><td>1.61</td></tr> <tr><td>Web Files</td><td>1.03</td></tr> </tbody> </table> | Hardware | | Model | Part Number (P/N) | RBMS Plus 1 String | 0370260-002 | RBMS Plus 2 Strings | 0370260-003 | | | Software / Firmware | | Model | Revision | Firmware | 1.61 | Web Files | 1.03 |
| Hardware | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Model | Part Number (P/N) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| N/A | N/A | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Software / Firmware | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Model | Revision | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Firmware | 1.61 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Web Files | 1.05A | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Hardware | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Model | Part Number (P/N) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RBMS Plus 1 String | 0370260-002 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RBMS Plus 2 Strings | 0370260-003 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Software / Firmware | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Model | Revision | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Firmware | 1.61 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Web Files | 1.03 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7. New CLEI Code N/A | 8. Old CLEI Code N/A | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 9. Associated Products or Changes Affected 0260024-027, 0260024-052, 0380391-001 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10. Drawing Number N/A | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 11. Classification of Change B | 12. Reason for Classification Product change which was made to incorporate improvement in the design that result in better operation. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |



an EnerSys company

Product Change Notification

| | |
|---|---|
| 13. Reason for Change When temperature drops below 0°C (32°F), the webpage displays a high value in the temperature field. | |
| 14.1 Description of Change New web files software is released to fix the bug that caused web page to display negative temperatures incorrectly. | |
| 14.2 Change Verification Procedures Software Verification – Login to webpages and click on "Site Data" section to confirm Web Version is 1.05A | |
| 15. Safety Notification N/A | |
| 16. Material Affected N/A | |
| 17. Documentation Affected N/A | |
| 18. Supplier Implementation Date This is a phase in change and new software will be implemented into product shipping from the factory in Q2, 2021. | 19. Modification Completion Date Q3, 2021 |
| 20. Modification Location Factory and in the field | |
| 21. Modification Cost N/A | |
| 22. Location and Quantity of Equipment N/A | |
| 23. Attachments N/A | |
| 24. Comments N/A | |