



May 9, 2012

PRODUCT CHANGE NOTIFICATION

PCN # [1120430]

[CXCR/P Pathfinder Support]

Subject:

Pathfinder rectifier support (List 92) is no longer a default option on Cordex CXCR/P series controllers. The option is still available for support of legacy Pathfinder rectifiers via the part numbers as listed below.

Products Affected:

- *All 018-557-20-xxx controllers with exception of following SKU's:*
 - *018-557-20-151 (48V Rack Mount)*
 - *018-557-20-063 (24V Rack Mount)*
- *Any power system configuration (e.g., 026*, 053*, 057*, etc) which includes CXCR/CXCP controller configurations*

Change Description:

The RS485 communications port (List 92) will not be populated on the PCBA of the CXCR/P with the exception of models listed above.

Reason for Change:

Legacy rectifier module support no longer required in majority of applications.

Key Dates:

As of May 15th, 2012, all CXCR/P controllers (and systems with embedded CXCR/P controllers) will ship without a RS485 connection for Pathfinder rectifier support with the exception of the two products listed above.

Contact:

For any questions regarding this PCN, please contact Bill Killion, Alpha Product Manager for Controller Products:

Phone: 604-422-4487

Email: bill.killion@alpha.ca