



an EnerSys company

PCN # 0470449-PCN

RBMS Plus Firmware Upgrade to enable webpages without JAVA plugins

1. Supplier Information Alpha Technologies, Ltd. 7700 Riverfront Gate Burnaby, BC V5J 5M4 Canada	1.6 Supplier Contact Info Contact: Daljit Hothi Product Manager 604 422 4490 daljit.hothi@alpha.ca																																												
2. Product Change Notification Number PCN # 0470449-PCN	3. Issue Date of Change 3/31/2020																																												
4. System Affected Major System Affected: RBMS Plus Subsystem Affected: N/A Hardware Affected: N Firmware Affected: Y Software Affected: Y																																													
5. New Product ID <table border="1" data-bbox="116 1184 698 1570"> <thead> <tr><th colspan="2">Hardware</th></tr> <tr><th>Model</th><th>Part Number (P/N)</th></tr> </thead> <tbody> <tr><td>N/A</td><td>N/A</td></tr> <tr><td> </td><td> </td></tr> <tr><td> </td><td> </td></tr> <tr><td> </td><td> </td></tr> <tr><th colspan="2">Software / Firmware</th></tr> <tr><th>Model</th><th>Revision</th></tr> <tr><td>Firmware</td><td>1.61</td></tr> <tr><td>Web Files</td><td>1.03</td></tr> <tr><td> </td><td> </td></tr> </tbody> </table>	Hardware		Model	Part Number (P/N)	N/A	N/A							Software / Firmware		Model	Revision	Firmware	1.61	Web Files	1.03			6. Old Product ID <table border="1" data-bbox="876 1184 1458 1570"> <thead> <tr><th colspan="2">Hardware</th></tr> <tr><th>Model</th><th>Part Number (P/N)</th></tr> </thead> <tbody> <tr><td>RBMS Plus 1 string</td><td>0370260-002</td></tr> <tr><td>RBMS Plus 2 strings</td><td>0370260-003</td></tr> <tr><td> </td><td> </td></tr> <tr><td> </td><td> </td></tr> <tr><th colspan="2">Software / Firmware</th></tr> <tr><th>Model</th><th>Revision</th></tr> <tr><td>Firmware</td><td>1.40</td></tr> <tr><td>Web Files</td><td>1.30</td></tr> <tr><td> </td><td> </td></tr> </tbody> </table>	Hardware		Model	Part Number (P/N)	RBMS Plus 1 string	0370260-002	RBMS Plus 2 strings	0370260-003					Software / Firmware		Model	Revision	Firmware	1.40	Web Files	1.30		
Hardware																																													
Model	Part Number (P/N)																																												
N/A	N/A																																												
Software / Firmware																																													
Model	Revision																																												
Firmware	1.61																																												
Web Files	1.03																																												
Hardware																																													
Model	Part Number (P/N)																																												
RBMS Plus 1 string	0370260-002																																												
RBMS Plus 2 strings	0370260-003																																												
Software / Firmware																																													
Model	Revision																																												
Firmware	1.40																																												
Web Files	1.30																																												
7. New CLEI Code N/A	8. Old CLEI Code N/A																																												
9. Associated Products or Changes Affected 0260024-027, 0260024-052 & 0380391-001																																													
10. Drawing Number N/A																																													



an EnerSys company

11. Classification of Change B	12. Reason for Classification Product change which was made to incorporate improvement in the design that result in better operation, improved testing/maintenance, longer life, operational cost reduction and/or addition of new features.
13. Reason for Change Java plugins are required for web page access. Some users are not allowed to install Java plugin on their computers.	
14.1 Description of Change Firmware update removes Java plugins from the software and is designed for Chrome and Edge web browsers.	
14.2 Change Verification Procedures N/A	
15. Safety Notification N/A	
16. Material Affected N/A	
17. Documentation Affected RBMS Manual 0370260-J0	
18. Supplier Implementation Date This is a phase in change and new firmware will be implemented into product shipping from the factory in Q2, 2020. Software is available at http://www.alpha.ca/softwarefirmwaredownloads	19. Modification Completion Date Q3, 2020
20. Modification Location N/A	
21. Modification Cost N/A	
22. Location and Quantity of Equipment N/A	
23. Attachments N/A	
24. Comments N/A	