



an EnerSys® company

# Product Change Notification

## PCN # 0470487-PCN RMBS Plus Firmware Version 1.63

<b>1. Supplier Information</b> Alpha Technologies, Ltd. 7700 Riverfront Gate Burnaby, BC V5J 5M4 Canada	<b>1.2 Supplier Contact Information</b> Contact: Daljit Hothi Product Manager 604 422 4490 <a href="mailto:daljit.hothi@enersys.com">daljit.hothi@enersys.com</a>																																		
<b>2. Product Change Notification Number</b> PCN # 0470487-PCN	<b>3. Issue Date of Change</b> August 5, 2021																																		
<b>4. System Affected</b> Major System Affected: RMBS Plus Subsystem Affected: N/A Hardware Affected: No Firmware Affected: Yes Software Affected: No																																			
<b>5. New Product ID</b> <table border="1" data-bbox="167 1325 777 1770"> <thead> <tr><th colspan="2">Hardware</th></tr> <tr><th>Model</th><th>Part Number (P/N)</th></tr> </thead> <tbody> <tr><td>N/A</td><td>N/A</td></tr> <tr><td colspan="2"> </td></tr> <tr><th colspan="2">Software / Firmware</th></tr> <tr><th>Model</th><th>Revision</th></tr> <tr><td>Firmware</td><td>1.63</td></tr> <tr><td>Web Files</td><td>1.05A</td></tr> </tbody> </table>	Hardware		Model	Part Number (P/N)	N/A	N/A			Software / Firmware		Model	Revision	Firmware	1.63	Web Files	1.05A	<b>6. Old Product ID</b> <table border="1" data-bbox="846 1325 1456 1770"> <thead> <tr><th colspan="2">Hardware</th></tr> <tr><th>Model</th><th>Part Number (P/N)</th></tr> </thead> <tbody> <tr><td>RMBS Plus 1 String</td><td>0370260-002</td></tr> <tr><td>RMBS Plus 2 Strings</td><td>0370260-003</td></tr> <tr><td colspan="2"> </td></tr> <tr><th colspan="2">Software / Firmware</th></tr> <tr><th>Model</th><th>Revision</th></tr> <tr><td>Firmware</td><td>1.61</td></tr> <tr><td>Web Files</td><td>1.05A</td></tr> </tbody> </table>	Hardware		Model	Part Number (P/N)	RMBS Plus 1 String	0370260-002	RMBS Plus 2 Strings	0370260-003			Software / Firmware		Model	Revision	Firmware	1.61	Web Files	1.05A
Hardware																																			
Model	Part Number (P/N)																																		
N/A	N/A																																		
Software / Firmware																																			
Model	Revision																																		
Firmware	1.63																																		
Web Files	1.05A																																		
Hardware																																			
Model	Part Number (P/N)																																		
RMBS Plus 1 String	0370260-002																																		
RMBS Plus 2 Strings	0370260-003																																		
Software / Firmware																																			
Model	Revision																																		
Firmware	1.61																																		
Web Files	1.05A																																		



an EnerSys® company

## Product Change Notification

<b>7. New CLEI Code</b> N/A	<b>8. Old CLEI Code</b> N/A
<b>9. Associated Products or Changes Affected</b> 0260024-027, 0260024-052, 0380391-001	
<b>10. Drawing Number</b> N/A	
<b>11. Classification of Change</b> B	<b>12. Reason for Classification</b> This change results in better operation.
<b>13. Reason for Change</b> RBMS Plus JAVA free webpages will not populate or will take significant time to load with a cellular modem.	
<b>14.1 Description of Change</b> New firmware is released to update MTU size so webpage data will populate via a cellular modem.	
<b>14.2 Change Verification Procedures</b> Firmware Verification – Login to webpages and select <b>Site Data</b> section to confirm. Firmware Version is 1.63	
<b>15. Safety Notification</b> N/A	
<b>16. Material Affected</b> N/A	
<b>17. Documentation Affected</b> N/A	



an EnerSys® company

## Product Change Notification

<b>18. Supplier Implementation Date</b> This is a phase in change and new firmware will be implemented into product shipping from the factory in Q3, 2021.	<b>19. Modification Completion Date</b> Q4, 2021
<b>20. Modification Location</b> Factory and in the field	
<b>21. Modification Cost</b> N/A	
<b>22. Location and Quantity of Equipment</b> N/A	
<b>23. Attachments</b> N/A	
<b>24. Comments</b> N/A	

End of Product Change Notification